



Photo: 6

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: East wet cake pile

Direction Facing: Southwest

Description: This photo depicts the berm containment around the east wet cake pile. The berm is not breaching at this time but is at capacity. I instructed Mr. Peterson to maintain this area by adding dirt and pumping.



Photo: 7

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: East wet cake pile

Direction Facing: Southwest

Description: This photo depicts the berm containment around the east wet cake pile (arrow). The photo depicts the berm from the west side of the water way.





Photo: 7

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: North wet cake pile

Direction Facing: West

Description: This photo depicts the northwest corner of the northwest lagoon. There is accumulated water inside the berm. There is also some rainwater accumulation behind the berm (arrow). There is no evidence of leaking at this time.



Photo: 8

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: South lagoon

Direction Facing: East

Description: This photo depicts the south lagoon. The lagoon appears lower than it did on Monday March 15, 2021.





Photo: 9

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: South lagoon

Direction Facing: North

Description: This photo depicts the south lagoon.