



Photo: 10 Site Visit Report

Date Taken: 3-17-2021 Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: South lagoon Direction Facing: North

Description: This photo depicts a possible tear in the south lagoon liner (arrow). This is located along the

south lagoon dike.

## NEBRASKA



Photo: 11 Site Visit Report Date Taken: 3-17-2021 Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: Northeast lagoon Direction Facing: East

Description: This photo depicts a torn liner floating against the south dike.

## NEBRASKA

DEPT. OF ENVIRONMENT AND ENERGY



Photo: 12 Site Visit Report

Date Taken: 3-17-2021 Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: Northeast lagoon Direction Facing: North

Description: This photo depicts multiple whales in the northeast lagoon. The whales appear to be slightly

smaller today.