



Photo: 13

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: Northeast lagoon

Direction Facing: North

Description: This photo depicts the equalization tube between the South and the Northeast lagoon. It appears that the south lagoon is flowing into the northeast lagoon. Notice the difference in color (circle).



Photo: 14

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: Between the northeast and south lagoon

Direction Facing: East

Description: This photo depicts the dikes between the northeast and south lagoon. The photo also depicts the equalization tube between the two lagoons. There is lots of wave action in the northeast lagoon while the south lagoon is smooth.



Photo: 15

Site Visit Report

Date Taken: 3-17-2021

Photographer: Mark Pomajzl

Facility Name/ Project Name: AltEn LLC

Facility IIS number / Project identifier: IIS: 84069 / NE0137634

Location: Between the northeast and northwest lagoon

Direction Facing: North

Description: This photo depicts between the northeast and northwest lagoon. The photo also depicts the equalization tube..