



Above Verde Springs Total Arsenic

(Standard: 0.030)





Perkinsville Total Arsenic

(Standard: 0.030)




Arsenic measurements were taken from 2006-2012, then stopped.
Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.



Arsenic measurements were taken from 2006-2012, then stopped.
Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.


White Bridge Total Arsenic

(Standard: 0.030)




Black Bridge Total Arsenic

(Standard: 0.030)



Arsenic measurements were taken from 2006-2012, then stopped.
Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.

Beasley Flat Total Arsenic (Standard: 0.030)



Arsenic measurements were taken from 2006-2012, then stopped.
Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.