Hartford Comparative Leak Reports



Figure 1. Reports To PURA– October 15, 2015 to October 17, 2016. Graph showing 7-2 highlighted is yellow. Totals are: 2 streets x 7 leaks; 3 (st.) x 4 (lk); 7 (st.) x 3 (lk); 17 x 2; 58 x 1 per street. TOTAL 139.



Figure 2. Tests by Gas Safety Inc. - February 25, 2016 to March 31, 2016. Graph showing 26 – 6 highlighted in yellow. Totals are: 1 streets x 26 leaks; 2 streets x 17 leaks; 1 x 16; 1 x 15; 2 x 12; 1 x 11; 3 x 9; 3 x 8; 2 x 7; 7 x 6; 14 x 5; 21 x 4; 33 x 3; 2 x 48; 1 x 122 per street. TOTAL 704.