



Above Verde Springs Total Phosphorus (Standard: 1.000)




Perkinsville Total Phosphorus (Standard: 1.000)




Phosphorus measurements were taken from 2006-2011, then stopped as no exceedances had been observed. Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.

Reitz Total Phosphorus (Standard: 1.000)




89A Bridge Total Phosphorus (Standard: 1.000)



Phosphorus measurements were taken from 2006-2011, then stopped as no exceedances had been observed. Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.


White Bridge Total Phosphorus

(Standard: 1.000)




Black Bridge Total Phosphorus

(Standard: 1.000)



Phosphorus measurements were taken from 2006-2011, then stopped as no exceedances had been observed. Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.

Beasley Flat Total Phosphorus (Standard: 1.000)



Phosphorus measurements were taken from 2006-2011, then stopped as no exceedances had been observed. Monitoring at White Bridge ceased in 2010, and a new site at Black Bridge was added at that time.